

LIFT PRODUCTION BY YEAR

| | 1993 | 1994 | 1995 | 1996 | 1997 | 1998 | 1999 | 2000 | 2001 | 2002 | 2003 | 2004 | 2005 | 2006 | 2007 | 2008 | 2009 | 2010 | 2011 | 2012 | 2013 | 2014 | 2015 | 2016 | 2017 | |
|---------------------------------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|---|
| CANTILEVER LIFTS | | | | | | | | | | | | | | | | | | | | | | | | | | |
| ACL8 | ● | | | | | | | | | | | | | | | | | | | | | | | | | |
| ACL10* | | ● | | | | | | | | | | | | | | | | | | | | | | | | |
| ACL16 | ● | ● | | | | | | | | | | | | | | | | | | | | | | | | |
| ACL26 | ● | ● | | | | | | | | | | | | | | | | | | | | | | | | |
| BCL36* | ● | ● | | | | | | | | | | | | | | | | | | | | | | | | |
| BCL36120* | ● | ● | | | | | | | | | | | | | | | | | | | | | | | | |
| BCL36S108 | ● | ● | ● | | | | | | | | | | | | | | | | | | | | | | | |
| BCL36S120 | ● | ● | ● | | | | | | | | | | | | | | | | | | | | | | | |
| BCL46* | ● | ● | | | | | | | | | | | | | | | | | | | | | | | | |
| BCL46120* | ● | ● | | | | | | | | | | | | | | | | | | | | | | | | |
| BCL46S108 | ● | ● | ● | | | | | | | | | | | | | | | | | | | | | | | |
| BCL46S120 | ● | ● | ● | | | | | | | | | | | | | | | | | | | | | | | |
| BCL56* | ● | ● | | | | | | | | | | | | | | | | | | | | | | | | |
| BCL56120* | ● | ● | | | | | | | | | | | | | | | | | | | | | | | | |
| BCL70132* | ● | ● | | | | | | | | | | | | | | | | | | | | | | | | |
| LSC36108* | | | | ● | | | | | | | | | | | | | | | | | | | | | | |
| LSC36120* | | | | ● | | | | | | | | | | | | | | | | | | | | | | |
| LSC46108* | | | | ● | | | | | | | | | | | | | | | | | | | | | | |
| LSC46120* | | | | ● | | | | | | | | | | | | | | | | | | | | | | |
| CANTILEVER PONTOON LIFTS | | | | | | | | | | | | | | | | | | | | | | | | | | |
| LSP16 | ● | ● | ● | ● | ● | | | | | | | | | | | | | | | | | | | | | |
| LSP21 | ● | ● | ● | ● | ● | | | | | | | | | | | | | | | | | | | | | |
| LSP24 | ● | ● | ● | ● | ● | | | | | | | | | | | | | | | | | | | | | |
| LSP28 | ● | ● | | ● | ● | | | | | | | | | | | | | | | | | | | | | |
| LSP16H | | | | | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● |
| LSP21H | | | | | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● |
| LSP24H | | | | | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● |
| LSP28H | | | | | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● | ● |

* exploded views are not available

LIFT PRODUCTION BY YEAR

| | 1993 | 1994 | 1995 | 1996 | 1997 | 1998 | 1999 | 2000 | 2001 | 2002 | 2003 | 2004 | 2005 | 2006 | 2007 | 2008 | 2009 | 2010 | 2011 | 2012 | 2013 | 2014 | 2015 | 2016 | 2017 |
|-----------------------------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|
| CANTILEVER PWC LIFTS | | | | | | | | | | | | | | | | | | | | | | | | | |
| JL | • | • | | | | | | | | | | | | | | | | | | | | | | | |
| JLD | • | • | | | | | | | | | | | | | | | | | | | | | | | |
| JLD2 | | • | • | • | • | | | | | | | | | | | | | | | | | | | | |
| JLS | • | • | • | | | | | | | | | | | | | | | | | | | | | | |
| LSC1264 | | | | | | | | | | | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • |
| LSC1480 | | | | | | | | | • | • | | | | | | | | | | | | | | | |
| LSC1488 | | | | • | • | • | • | • | | | | | | | | | | | | | | | | | |
| LSC1576 | | | | | | | | | | | | | | | | | • | • | • | • | • | • | • | • | • |
| LSC648 | | | | • | • | • | | | | | | | | | | | | | | | | | | | |
| LSC650 | | | | | | | • | • | • | • | • | • | • | • | • | • | • | • | • | | | | | | |
| LSC750D | | | | | | | • | • | • | • | • | • | • | • | • | • | • | • | • | | | | | | |
| LSC850 | | | | | | | | | | | | | | | | | | | | • | • | • | • | • | • |
| LSC850D | | | | | | | | | | | | | | | | | | | | • | • | • | • | • | • |
| LSC860 | | | | • | • | • | • | • | | | | | | | | | | | | | | | | | |
| LSC860D | | | | | | • | | | | | | | | | | | | | | | | | | | |
| LSC964 | | | | | | | | • | • | • | • | • | • | • | • | • | • | • | • | | | | | | |
| CANOPY FRAMES | | | | | | | | | | | | | | | | | | | | | | | | | |
| Canopy Frame | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • |
| Canopy Frame : LSC1264 | | | | | | | | | | | | | | | | | | | | | | • | • | • | • |
| Canopy Frame : LSV1364 | | | | | | | | | | | | | | | | | | | | | | • | • | • | • |
| Freestanding Canopy Leg Kit | | | | | | | | | | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • |

LIFT PRODUCTION BY YEAR

| | 1993 | 1994 | 1995 | 1996 | 1997 | 1998 | 1999 | 2000 | 2001 | 2002 | 2003 | 2004 | 2005 | 2006 | 2007 | 2008 | 2009 | 2010 | 2011 | 2012 | 2013 | 2014 | 2015 | 2016 | 2017 |
|----------------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|------|
| VERTICAL LIFTS | | | | | | | | | | | | | | | | | | | | | | | | | |
| LSV1364 | | | | | | | | | | | | | | | | | | | • | • | • | • | • | • | • |
| LSV15100 | | | • | | | | | | | | | | | | | | | | | | | | | | |
| LSV20100 | | | | • | • | • | • | | | | | | | | | | | | | | | | | | |
| LSV36108 | | | | • | • | • | • | | | | | | | | | | | | | | | | | | |
| LSV36120 | | | | • | • | • | • | | | | | | | | | | | | | | | | | | |
| LSV40108/4108 | • | • | • | | | | | | | | | | | | | | | | | | | | | | |
| LSV46108 | | | | • | • | • | • | | | | | | | | | | | | | | | | | | |
| LSV46120 | | | | • | • | • | • | | | | | | | | | | | | | | | | | | |
| LSV20100A | | | | | | | | • | • | • | • | | | | | | | | | | | | | | |
| LSV36108A | | | | | | | • | • | • | | | | | | | | | | | | | | | | |
| LSV36120A | | | | | | | • | • | • | | | | | | | | | | | | | | | | |
| LSV40108A | | | | | | | • | • | • | | | | | | | | | | | | | | | | |
| LSV46108A | | | | | | | • | • | • | | | | | | | | | | | | | | | | |
| LSV50120A | | | | | | | • | • | • | • | • | • | | | | | | | | | | | | | |
| LSV20100B | | | | | | | | | | | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • |
| LSV30108B | | | | | | | | | | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • |
| LSV30120B | | | | | | | | | | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • |
| LSV40108B | | | | | | | | | | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • |
| LSV40120B | | | | | | | | | | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • | • |
| LSV50120B | | | | | | | | | | | | • | • | • | • | • | • | • | • | • | • | • | • | • | • |
| LSV30120BP | | | | | | | | | | | | • | • | • | • | • | • | • | • | • | • | • | • | • | • |
| LSV40120BP | | | | | | | | | | | | • | • | • | • | • | • | • | • | • | • | • | • | • | • |
| LSV50120BP | | | | | | | | | | | | | | | | | | | • | • | • | • | • | • | • |
| LSV30120BP-U | | | | | | | | | | | | | • | • | • | • | • | • | • | • | • | • | • | • | • |
| LSV40120BP-U | | | | | | | | | | | | | • | • | • | • | • | • | • | • | • | • | • | • | • |
| LSV50120BP-U | | | | | | | | | | | | | | | | | | | • | • | • | • | • | • | • |
| LSV20100C | | | | | | | | | | | | | | | | | | | | | | | | | • |
| LSV30108C | | | | | | | | | | | | | | | | | | | | | | | | | • |
| LSV30120C | | | | | | | | | | | | | | | | | | | | | | | | • | • |
| LSV40108C | | | | | | | | | | | | | | | | | | | | | | | | | • |
| LSV40120C | | | | | | | | | | | | | | | | | | | | | | | | • | • |
| LSV50120C | | | | | | | | | | | | | | | | | | | | | | | | • | • |
| LSV75120C | | | | | | | | | | | | | | | | | | | | | | | | | • |
| LSV30120CP | | | | | | | | | | | | | | | | | | | | | | | | • | • |
| LSV40120CP | | | | | | | | | | | | | | | | | | | | | | | | • | • |
| LSV50120CP | | | | | | | | | | | | | | | | | | | | | | | | • | • |
| LSV75120CP | | | | | | | | | | | | | | | | | | | | | | | | | • |
| LSV30120CP-U | | | | | | | | | | | | | | | | | | | | | | | | • | • |
| LSV40120CP-U | | | | | | | | | | | | | | | | | | | | | | | | • | • |
| LSV50120CP-U | | | | | | | | | | | | | | | | | | | | | | | | • | • |
| LSV75120CP-U | | | | | | | | | | | | | | | | | | | | | | | | | • |